

Measuring Ambient Radiation Levels

Monitoring Post




Survey Meters



Nal Scintillation type (mainly measures low-levels)



Csl Scintillation type, etc. (mainly measures low-levels)



Ionization Chamber (measures low to high-level radiation)



³He Counter Tube type (measures neutron radiation)