


Measuring Ambient Radiation Levels

Monitoring Post




Survey Meters




NaI Scintillation type
(mainly measures low-levels)



CsI Scintillation type, etc.
(mainly measures low-levels)



Ionization Chamber
(measures low to high-level radiation)



³He Counter Tube type
(measures neutron radiation)